

Antea USA, Inc. 4940 Peachtree Industrial Boulevard, Suite 350 Norcross, Georgia 30071 www.anteagroup.com

July 9, 2013

Mr. Jim McAdoo
Tennessee Department of Environment and Conservation
Division of Water Resources
Permit Section
6th Floor L & C Annex
401 Church Street
Nashville, TN 37243-1534

RE: Underground Storage Tank (UST) Remediation – NPDES Permit Renewal

Permit Number TNG830000

Permit Tracking Number: TNG830129

Former BP Service Station - BP Site No. 24368

222 Shelby Avenue Nashville, Tennessee

TDEC Facility ID No. 95-190964

Antea Group Project No. TN24368131

RECEIVED

JUL 1 5 2013

TN Division Of Water Pellution Control

Dear Mr. McAdoo:

Antea™Group submits this request on to the Tennessee Department of Environment and Conservation (TDEC), Division of Water Resources, regarding the referenced site permitted under the General NPDES Permit for Discharges of Treated Groundwater Associated with Underground Storage Tank Remediation (RMCP), Permit Number TNG830000 having a Permit Tracking Number of TNG830129, for the UST Remediation TDEC Facility ID. No. 95-190964.

Antea™Group completed the approved remediation work for the Former BP Service Station – BP Site No. 24368 as directed by the TDEC- UST Division and will not discharge treated wastewater from this site in the future.

The TDEC UST Division issued a "Termination of Corrective Action/ Closure Monitoring" letter to BP Products North America Inc. (BP) on December 16, 2011 stating that no additional corrective action should be conducted at the referenced site (Attachment I). The groundwater remediation system or Corrective Action System (CAS) was placed offline and deactivated in January 2012. There were no treated groundwater discharges after the CAS was deactivated.



Mr. Jim McAdoo TDEC Division of Water Resources Permit Section July 9, 2013 Page 2

RECEIVED

JUL 1 5 2013

TN Division Of Water Pallution Control

The TDEC UST January 18, 2013 correspondence directed BP to properly abandon all monitoring and recovery wells associated with the site and to properly decommission the CAS (Attachment II).

A soil sampling event and four groundwater monitoring events were performed from January 2012 through December 2012. The last NPDES Discharge Monitoring Report was submitted to the Division of Water Resources on January 31, 2013 (Attachment III) which indicated no discharges occurred after the CAS was deactivated.

The Monitoring Well Abandonment and Corrective Action System Decommissioning Report was submitted to TDEC-UST on April 4, 2013. A copy of the letter report without attachments is presented in **Attachment IV**.

Antea™Group understands that the General NPDES Permit for Discharges of Treated Groundwater Associated with UST Remediation (RMCP), Permit Number TNG830000, was reissued on June 1, 2013 and effective on July 1, 2013.

We do not plan to submit a Notice of Intent (NOI) to renew our NPDES permit (Permit Number TNG830000 having a Permit Tracking Number of TNG830129) because we will not discharge any treated wastewater from this source in the future. We request that you review the attached information and close the administrative file for this NPDES permit associated with the referenced site.

Our office is moving to a new location at 4940 Peachtree Industrial Blvd., Suite 350, Norcross, Georgia 30071. If you have any questions or comments, please do not hesitate to contact me at (404) 542-2298.

Sincerely,

Kenneth L. Brooke, P.E.

Project Manager

ken.brooke@anteagroup.com

Antea Group

Attachments

cc: Antea Group Project File

Carla Nascimento, Jimmy Wong and Michelle Dukes (Antea Group)

ATTACHMENT I

TDEC UST TERMINATION OF CORRECTIVE ACTION

AND

CLOSURE MONITORING LETTER

JUL 1 5 2013

TN Division Of Water Pollution Control



NASHVILLE ENVIRONMENTAL FIELD OFFICE TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION

711 R.S.Gass Blvd Nashville, TENNESSEE 37243 (615) 687-7000 STATEWIDE 1-888-891-8332 FAX (615) 687-7078

December 16, 2011

Ms. Janet J. Wager BP Products North America, Inc. 201 Helios Way, Sixth Floor Houston, TX 77079

RE: Termination of Corrective Action / Closure Monitoring BP Site #24368 222 Shelby Avenue, Nashville, Tennessee Facility ID # 5-190964, Davidson County FECEIVED

JUL 1 5 2013

TN Division Ci Water Peliution Control

Dear Ms. Wager:

The Division of Underground Storage Tanks (Division) has reviewed the Corrective Action Monitoring Report dated December 5, 2011. Groundwater analytical data indicate the Chemicals of Concern (COCs) concentrations are below the approved site-specific standards and free product is no longer detected. Therefore, the Division requires that BP Products North America, Inc. deactivate the Corrective Action System (CAS) in accordance with the enclosed System Deactivation Checklist. No additional corrective action shall be conducted, unless directed otherwise by the Division. The CAS shall be placed offline by January 6, 2012 and shall be maintained and ready for operation. The Deactivation Checklist shall be completed and submitted with the first Corrective Action Closure Monitoring Report (CACMR).

Corrective Action (CA) Closure Monitoring shall be conducted and reported in accordance with the Approved CAP and the current CAP Guidelines and as directed below by the Division. All monitoring and recovery wells shall be sampled during the first and fourth CA closure monitoring events. Monitoring well MW-2 and MW-13 and recovery well RW-3 shall be sampled during the second and third CA closure monitoring events.

Soil sampling shall be conducted during the first CA closure monitoring event in the vicinity of where soil concentrations historically exceeded the approved Site Specific Cleanup Levels (SSCLs). Soil sampling shall be conducted in the vicinity of MW-2 from (19' to 21') below ground surface (bgs) and in the vicinity of MW-3 from (14' to 16') bgs. Soil samples shall not be collected from the saturation zone. If groundwater is encountered before the aforementioned intervals, soil samples shall be collected from immediately above the groundwater interface. All soil and groundwater samples shall be analyzed for the COCs listed in the site-specific standard.

Ms. Janet J. Wager BP Products North America, Inc. Facility ID #5-190964 December 16, 2011 Page 2

In accordance with rule 1200-01-15-.06(1), this office must be notified at least one working day in advance of any field activities.

CACMRs shall be submitted as follows:

Report	Submittal Date
CACMR	April 16, 2012
CACMR	July 16, 2012
CACMR	October 16, 2012
CACMR	January 16, 2013

Submit an original of all correspondence and reports to this field office and a copy to:

Division of Underground Storage Tanks
Tennessee Department of Environment and Conservation
4th Floor, L & C Tower
401 Church Street
Nashville, TN 37243-1541

All forms and guidance are available at www.tn.gov/environment/ust.

If you have any questions concerning this correspondence, call (615) 687-7095.

Sincerely,

Drew Storm, P.G.

Environmental Specialist

Division of Underground Storage Tanks

Enclosure: System Deactivation Checklist

c: Ms. Carla Nascimento - Antea Group

Mr. Kenneth Brooke - Antea Group

Ms. Michelle Dukes - Antea Group

Mr. Walter Overton - Cumberland Stadium, Inc.

Mr. Dempsey Henderson - Cumberland Stadium, Inc.

Mr. Emmett Edwards - Nashville Sports Authority

UST Central Office - Technical File

Nashville UST Field Office Case File #5-190964

JUL 1 5 2013

The Division Of Water Pallution Control

Corrective Action System Deactivation Checklist

Page 1

Lancard Control of the Control of th				1 460 1
Facility ID #:	CAP approval date:			
Facility name:	CAS TDEC Tag ID#:			
Facility address:	CAS manufacturer ID #:			
	CAS activation date:			
Facility (CAS) telephone #:				
CAC completing checklist:	CAS deactivation date(s):			
Person(s) completing checklist:	Time onsite:	Time offs	ite:	
CAS Dentityation Tasks:				
Receive closure monitoring (deactivation) letter from Division	,	□ Yes	□ No	
Dewater CAS inlet manifold		□ Yes	□ No	□ N/A
Close valves at CAS inlet manifold		☐ Yes	□ No	□ N/A
Dewater influent piping to AWS-1 inlet (ensure strainer/screen sec	cured in CAS, if available)	□ Yes	□ No	□ N/A
Clean and dewater AWS-1 stilling well and probes		□ Yes	□ No	□ N/A
Clean (e.g., remove sediments from) and dewater AWS-1 tank		□ Yes	□ No	□ N/A
Drain water from liquid ring pump and process piping and heat ex-	changer (if water-sealed system)	□ Yes	□ No	□ N/A
Winterization of liquid ring pump and heat exchanger (if water-sea			-	
in accordance with manufacturer's recommendations		□ Yes	□ No	□ N/A
Open air-relief valve (for air-assist compressor)		□ Yes	□ No	□ N/A
Close all air lines (for air-assist compressor)		□ Yes	□ No	□ N/A
Dewater all water treatment process piping and hosing		□ Yes	□ No	□ N/A
Close all water treatment process piping valves		□ Yes	□ No	□ N/A
Close all transfer pump valves and sample ports		□ Yes	□ No	□ N/A
Clean and dewater inlet air particulate filter housing	,	□ Yes	□ No	□ N/A
Clean oil strainer (if not conducted within last quarter)		☐ Yes	□ No	□ N/A
Close oil seal ball valve		□ Yes	□ No	□ N/A
Backwash carbon vessel(s)		☐ Yes	□ No	□ N/A
Drain excess water from carbon vessel(s)		☐ Yes	□ No	□ N/A
Open vents and/or valves at carbon vessel(s)		□ Yes	□ No	□ N/A
Remove fouled bag filter(s) and properly dispose		□ Yes	□ No	□ N/A
Clean and dewater bag filter vessel(s) (do not replace with new bag	g filters)	□ Yes	□ No	□ N/A
Clean and dewater Stripperator	7	□ Yes	□ No	□ N/A
Clean aeration tubes		□ Yes	□ No	□ N/A
Clean and dewater oil/water separator		□ Yes	□ No	□ N/A
Clean coalescing packing	а а	□ Yes	□ No	□ N/A
Clean and dewater Stripperator effluent sump		□ Yes	□ No	□ N/A
Clean Stripperator effluent sump probes		□ Yes	□ No	□ N/A
Clean and flush flow meter	, A	□ Yes	□ No	□ N/A
Open AWS-1, Stripperator, bag filter vessels and effluent sump lid	Is and covers (allow to air dry)	□ Yes	□ No	□ N/A
Close air flow dampers		□ Yes	□ No	□ N/A
Close air flow shroud inside and outside (sound box)		☐ Yes	□ No	□ N/A
Remove stack-pipe tops and place in CAS		☐ Yes	□ No	□ N/A
Tape open roof stacks		□ Yes	□ No	□ N/A
Place all breakers in control panel to off position		□ Yes	□ No	□ N/A
Place all controls to off position		☐ Yes	□ No	□ N/A
Place main breaker to off position and lock		□ Yes	□ No	□ N/A .
Unplug phone line from telemetry (inside control panel)		□ Yes	□ No	□ N/A



TR Division Oi Water Peliution Control

Corrective Action System Deactivation Checklist

Page 2

Facility ID #:			
Facility name:			
CASE Denofivation Trasks (cont.):			
Remove drop tubes (stingers) from recovery wells, rollup and place in CAS (allow to air dry)	□ Yes	□ No	□ N/A
Remove air-assist tubing from recovery wells, rollup and place in CAS (allow to air dry)	☐ Yes	□ No	□ N/A
Remove groundwater pumps, leads, hose and support line from recovery wells,	4		
rollup and place in CAS (allow to air dry)	□ Yes	□ No	□ N/A
Cap recovery wells and secure recovery well vaults	□ Yes	□ No	□ N/A
Cap and secure monitoring wells	☐ Yes	□ No	□ N/A
Secure CAS door, corners and control panel door	□ Yes	□ No	□ N/A
Number of drums onsite from O&M			,
Number of drums generated during deactivation activities			
Total number of drums properly disposed of (attach manifest)			
Drain and properly dispose of contents of free product tank (if applicable)	□ Yes	□ No	□ N/A
Total volume of liquid removed from free product tank and disposed of (attach manifest)			
Disconnect piping from CAS to free product tank	□ Yes	□ No	□ N/A
Cap ports at free product tank and leave vent(s) open	□ Yes	□ No	□ N/A
Tasks to be conducted during closure monitoring events:			
Re-energize CAS electricity, use on toggle switch to "bump" liquid-ring pump, transfer pumps and b	lower motor to	ensure o	perational
Check for vandalism - if observed - document and notify case manager			
Comments:			
Issues that TDEC and CAS manufacturer should be aware during refurbishment:			
e.g., MSP breaker tripped on a quarterly basis.			
•			

Refer to Reimbursement Guidance Document (RGD) - 002 for allowable deactivation task costs. Submit deactivation checklist with first Corrective Action Closure Monitoring Report (CACMR).

RECEIVED

JUL 1 8 7111

THE Division CI Water Pallution Control

ATTACHMENT II

MONITORING WELL ABANDONMENT

AND

CORRECTIVE ACTION SYSTEM DECOMMISSIONING LETTER

HECEIVED
JUL 1 5 2013

Tri Division Of Water Poliution Control



ENVIRONMENTAL FIELD OFFICE TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION 711 R.S. Gass Blvd

Nashville, Tennessee 37243 (615) 687-7000 STATEWIDE 1-888-891-8332

FAX (615) 687-7078

January 18, 2013

Ms. Janet J. Wager BP Products North America, Inc. 201 Helios Way, Sixth Floor Houston, TX 77079

Re: Monitoring Well Abandonment and Corrective Action System Decommissioning BP Site #24368
222 Shelby Avenue, Nashville, Tennessee
Facility ID # 5-190964, Davidson County

Dear Ms. Wager:

The Division of Underground Storage Tanks (Division) has reviewed the January 15, 2013 Corrective Action Closure Monitoring Report for the referenced facility. Additional monitoring and/or corrective action are not required.

BP Products North America, Inc. is required to properly abandon all monitoring and recovery wells in accordance with Section II.M. of the 2006 Environmental Assessment Guidelines. The corrective action system (CAS) shall be properly decommissioned using the enclosed CAS Decommission Checklist. Before this case can be closed, a monitoring well abandonment report, listing the wells abandoned and the driller license number and CAS Decommission Checklist shall be submitted to this field office by March 6, 2013.

Please notify the Division one working day prior to abandoning the monitoring wells in accordance with Rule 0400-18-01-.06(1).

All forms and guidance are available at www.tn.gov/environment/ust

If you have any questions concerning this correspondence, please do not hesitate to contact me at (615) 687-7095.

Drew Storm, P.G.

Sincerely,

Environmental Specialist

Division of Underground Storage Tanks

RECEIVED

.III 1 6 2013

TN Division Of Water Pollution Control

Corrective Action System Decommission Checklist

Page 1

Facility ID #:	CAP approval date:			
Facility name:	CAS TDEC Tag ID#:			
Facility address:	CAS manufacturer ID #:			
	CAS activation date:			
Facility (CAS) telephone #:				
CAC completing checklist:	CAS decommission date(s):			
Person(s) completing checklist:	Time onsite:	Time offs	site:	
CAS Decommission Tasks:				
Terminate electric account		□ Yes	□ No	□ N/A
Remove electric meter		□ Yes	□ No	□ N/A
Disconnect and remove electric line to CAS		□ Yes	□ No	□ N/A
Disassemble electrical riser and place in CAS		□ Yes	□ No	□ N/A
Remove temporary pole (if required)		□ Yes	□ No	□ N/A
Terminate water account/service (for water-sealed system)		□ Yes	□ No	□ N/A
Disconnect water line in accordance with local requirement	nts (for water-sealed system)	□ Yes	□ No	□ N/A
Terminate telephone account/service		□ Yes	□ No	□ N/A
Disconnect and remove telephone line to CAS		□ Yes	□ No	□ N/A
Terminate (water and/or air) discharge permit and/or according	unt	□ Yes	□ No	□ N/A
Disconnect and remove effluent piping from discharge poi	int in accordance with local requirements	□ Yes	□ No	□ N/A
Remove CAS inlet manifold and support		□ Yes	□ No	□ N/A
Close and secure all open valves, vents, lids and covers in	□ Yes	□ No	□ N/A	
Remove sound box and place in CAS	□ Yes	□ No	□ N/A	
Secure excess oil containers, filters and other miscellaneou	□ Yes	□ No	□ N/A	
Secure groundwater pumps in CAS	□ Yes	□ No	□ N/A	
Dispose of unusable stingers and downhole hosing		□ Yes	□ No	□ N/A
Monitoring and recovery wells abandoned		□ Yes	□ No	□ N/A
CAS removed from site		□ Yes	□ No	□ N/A
Free product tank and/or additional equipment removed fr	om site	□ Yes	□ No	□ N/A
Remove CAS concrete pad		□ Yes	□ No	□ N/A
Conduct site restoration		□ Yes	□ No	□ N/A
Check for vandalism - if observed - document and notify of	case manager			
Comments:				
Issues that TDEC and CAS manufacturer should be aware	during refurbishment:			
e.g., MSP breaker tripped on a quarterly basis.				

Refer to Reimbursement Guidance Document (RGD) - 002 for allowable decommission task costs. Submit decommission checklist with Monitoring Well Abandonment Report.





ENVIRONMENTAL FIELD OFFICE TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION 711 R.S. Gass Blvd

Nashville, Tennessee 37243 (615) 687-7000 STATEWIDE 1-888-891-8332

FAX (615) 687-7078

January 18, 2013

Ms. Janet J. Wager BP Products North America, Inc. 201 Helios Way, Sixth Floor Houston, TX 77079

Re: Monitoring Well Abandonment and Corrective Action System Decommissioning BP Site #24368
222 Shelby Avenue, Nashville, Tennessee
Facility ID # 5-190964, Davidson County

Dear Ms. Wager:

The Division of Underground Storage Tanks (Division) has reviewed the January 15, 2013 Corrective Action Closure Monitoring Report for the referenced facility. Additional monitoring and/or corrective action are not required.

BP Products North America, Inc. is required to properly abandon all monitoring and recovery wells in accordance with Section II.M. of the 2006 Environmental Assessment Guidelines. The corrective action system (CAS) shall be properly decommissioned using the enclosed CAS Decommission Checklist. Before this case can be closed, a monitoring well abandonment report, listing the wells abandoned and the driller license number and CAS Decommission Checklist shall be submitted to this field office by March 6, 2013.

Please notify the Division one working day prior to abandoning the monitoring wells in accordance with Rule 0400-18-01-.06(1).

All forms and guidance are available at www.tn.gov/environment/ust

If you have any questions concerning this correspondence, please do not hesitate to contact me at (615) 687-7095.

Drew Storm, P.G.

Sincerely,

Environmental Specialist

Division of Underground Storage Tanks

RECEIVED

rk Division Ci Waler Peliution Control Ms. Janet J. Wager BP Products North America, Inc. Facility ID #5-190964 January 18, 2013 Page 2

Ms. Carla Nascimento - Antea Group
 Mr. Kenneth Brooke - Antea Group
 Ms. Michelle Dukes - Antea Group
 Mr. Walter Overton - Cumberland Stadium, Inc.
 Mr. Dempsey Henderson - Cumberland Stadium, Inc.
 Mr. Emmett Edwards - Nashville Sports Authority
 UST Central Office - Technical File
 Nashville UST Field Office Case File #5-190964

fo-011/dps/19096401.1813

RECEIVED

JUL 1 8 2813
TR Division Of Water

Fallution Control

Corrective Action System Decommission Checklist

Page 1

Facility ID #:	CAP approval date:			1 age 1
Facility name:	CAS TDEC Tag ID#:			
Facility address:	CAS manufacturer ID #:			
denty address.	CAS activation date:			
Facility (CAS) telephone #:	CAS activation date.			
CAC completing checklist:	CAS decomplete detects			
Person(s) completing checklist:	CAS decommission date(s): Time onsite:	Tr: CC		
Control and Contro		Time offs	THE REST OF THE PARTY OF THE PA	
Terminate electric account				
Remove electric meter		□ Yes	□ No	□ N/A
Disconnect and remove electric line to CAS		□ Yes	□ No	□ N/A
Disassemble electrical riser and place in CAS		□ Yes	□ No	□ N/A
		□ Yes	□ №	□ N/A
Remove temporary pole (if required)		□ Yes	□ No	□ N/A
Terminate water account/service (for water-sealed system)		□ Yes	□ №	□ N/A
Disconnect water line in accordance with local requirements (for	water-sealed system)	□ Yes	□ №	□ N/A
Terminate telephone account/service		□ Yes	□ No	□ N/A
Disconnect and remove telephone line to CAS		□ Yes	. 🗆 No	□ N/A
Terminate (water and/or air) discharge permit and/or account		□ Yes	□ No	□ N/A
Disconnect and remove effluent piping from discharge point in ac	cordance with local requirements	□ Yes	□ No	□ N/A
Remove CAS inlet manifold and support		□ Yes	□ No	□ N/A
Close and secure all open valves, vents, lids and covers inside CA	S	□ Yes	□ No	□ N/A
Remove sound box and place in CAS		□ Yes	□ No	□ N/A
Secure excess oil containers, filters and other miscellaneous equip	ment inside CAS for transport	□ Yes	□ No	□ N/A
Secure groundwater pumps in CAS	i i	☐ Yes	□ No	□ N/A
Dispose of unusable stingers and downhole hosing		□ Yes	□ No	□ N/A
Monitoring and recovery wells abandoned		□ Yes	□ No	□ N/A
CAS removed from site		□ Yes	□ No	□ N/A
Free product tank and/or additional equipment removed from site		□ Yes	□ No	□ N/A
Remove CAS concrete pad		□ Yes	□ No	□ N/A
Conduct site restoration		□ Yes	□ No	□ N/A
Check for vandalism - if observed - document and notify case man	ager			
Comments:				
	•			
Issues that TDEC and CAS manufacturer should be aware during a	refurbishment:			
e.g., MSP breaker tripped on a quarterly basis.				
,				
	5			

Refer to Reimbursement Guidance Document (RGD) - 002 for allowable decommission task costs. Submit decommission checklist with Monitoring Well Abandonment Report.



ATTACHMENT III

NPDES DISCHARGE MONITORING REPORT - FOURTH QUARTER 2012





Antea USA, Inc. 5000 Peachtree Industrial Boulevard, Suite 160 Norcross, Georgia 30097 www.anteagroup.com

January 31, 2013

Mark Jordon
Environmental Specialist
Water Pollution Control Division
Enforcement and Compliance Section
Tennessee Department of Environment and Conservation
6th Floor L&C Annex
401 Church Street
Nashville, Tennessee 37243

RE: National Pollutant Discharge Elimination System Discharge Monitoring Report

Fourth Quarter 2012

Permit No. TNG830129, Discharge No. 001-G Former BP Service Station - BP Site No. 24368 222 Shelby Avenue Nashville, Tennessee TDEC Facility ID. No. 5-190964 Antea Group Project No. TN24368131

HECEIVED

TN Pivisian Gi Waler Paliutian Cantrol

Dear Mr. Jordon:

AnteaTMGroup submits the attached National Pollutant Discharge Elimination System (NPDES) Discharge Monitoring Report (DMR) — Fourth Quarter 2012 for the referenced facility. This report details the data collected during the monitoring period of October 1, 2012 through December 21, 2012, and includes one set of associated analytical data for Permit Number TNG830129, Discharge No. 001-G (Attachment I). Antea Group is the current BP Products North America Inc. (BP) contractor for the Former BP Service Station 24368, located at 222 Shelby Avenue, Nashville, Tennessee, 37213.

In a correspondence dated December 16, 2011, the Tennessee Department of Environment and Conservation (TDEC) determined that the groundwater analytical data indicated that the Chemicals of Concern (COC) concentration(s) were below the approved Site Specific Cleanup Levels (SSCL) and directed Antea Group to deactivate the Corrective Action System (CAS) in accordance with the CAS Deactivation Checklist. On December 22, 2011, the CAS at the site was deactivated in accordance with the TDEC Deactivation Checklist and has remained inoperable during this reporting period.



In a correspondence dated January 18, 2013, TDEC determined that additional monitoring and/or corrective action are not required at the site, and directed Antea Group to properly abandon all monitoring and recovery wells and to decommission the CAS at the site. A copy of the January 18, 2013 TDEC directive is presented as **Attachment II** for your review.

CAS decommissioning and monitoring and recovery well abandonment activities are scheduled to be conducted on February 13 through 14, 2013. As such, this will be the last NPDES DMR that Antea Group will be submitting to the Water Pollution Control Division Enforcement and Compliance Section for this site.

If you have any questions regarding this submittal please contact me at (404) 391-4892 or Ken Brooke at (770) 825-1227.

Sincerely,

J. Michelle Dukes

Project Professional

michelle.dukes@anteagroup.com

Unlia M. Dukes

Antea Group

RECEIVED

TR Division Of Water Pellution Control

Attachments: Analytical data for period of October 1, 2012 through December 21, 2012 Copy of the January 18, 2013 TDEC directive

cc: Antea Group Project File (Norcross)

ATTACHMENT I ANALYTICAL DATA TABLE

RECEIVED

JUL 1 5 2313

TR Sivisian Ci YYAIAT
Pallutian Centrel

STREET AMERICA INC 100 188-6619 3TATION (BP 24368)

NATIONAL DISCHARGE ELIMINATION SYSTEM(NPDES) DISCHARGE MONITORING REPORT (DMR)

TNG830129 PERMIT NUMBER 001-G
DISCHARGE NUMBER

	MONITORING PERIOD							
	YEAR	MO	DAY		YEAR	МО	DAY	
FROM	12	10	01	TO	12	12	31	

DMR MAILING ZIP CODE: 37213

MINOR (SUBR 04)

UST Remediation Treated Discharge

External Outfall

NO DISCHARGE ♣

	QUANT	TITY OR LOADI	NG	QI	UALITY OR CONCENTRATION		No.	FREQUENCY	SAMPLE	
	VALUE	VALUE	UNITS	VALUE	VALUE	VALUE	UNITS	EX	OF ANALYSIS	TYPE
SAMPLE										
EASUREMENT	*****	*****	*****	*****	NA	*****	SU	0	NA	NA
PERMIT				6.5		9				
EQUIREMENT	*****	*****	*****	DAILY MN	*****	DAILY MAX	SU	0	NA	NA
SAMPLE										
EASUREMENT	*****	*****	*****	*****	*****	NA	mg/L	0	NA	NA
PERMIT						40				
EQUIREMENT	*****	*****	*****	*****	*****	DAILY MX	mg/l	0	NA	NA
SAMPLE										
EASUREMENT	*****	*****	*****	*****	*****	NA	mg/L	0	NA	NA
PERMIT						.164				
EQUIREMENT	*****	*****	*****	*****	*****	Daily MX	mg/L	0	NA	NA
SAMPLE										
EASUREMENT	*****	*****	*****	*****	*****	NA	mg/L	0	NA	NA
PERMIT						.01		102.5		
EQUIREMENT	*****	*****	*****	*****	*****	DAILY MX	mg/L	0	NA	NA
SAMPLE										
EASUREMENT	*****	*****	*****	*****	*****	NA	mg/L	0	NA	NA
PERMIT						.005 DAILY				
EQUIREMENT	*****	*****	*****	*****	*****	MX	mg/L	0	NA	NA
SAMPLE										
EASUREMENT	*****	*****	*****	*****	*****	NA	mg/L	0	NA	NA
PERMIT						.01		15.00		
EQUIREMENT	*****	*****	*****	*****	*****	DAILY MX	mg/l	0	NA	NA
SAMPLE	1400000			200200000000000000000000000000000000000		1				
EASUREMENT	NA	*****	NA	*****	*****	*****	*****	0	NA	NA
PERMIT	Req. Mon.		Y=1;							
EQUIREMENT	VALUE	*****	N=0	*****	*****	*****	****	0	NA	NA
SAMPLE										
EASUREMENT	NA	*****	NA	*****	*****	*****	*****	0	NA	
PERMIT	Req. Mon.									
EQUIREMENT	DAILY MX	*****	Mgal/d	*****	*****	*****	****	0	NA	NA
SAMPLE	100000000000000000000000000000000000000		200000000000000000000000000000000000000	100000 17000 Link					******	
EASUREMENT	*****	*****	*****	*****	*****	NA	mg/L	0	NA	NA
PERMIT						.01				
EQUIREMENT	*****	*****	*****	*****	*****	Daily MX	mg/L	0	NA	NA

OFFICER			TELE	PHONE		DATE	
				I			
	I cently under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel property gather and evaluate the information submitted based on m.	Signature of Principal Executive Officer or Authorized Agent	AREA CODE	NUMBER	YEAR	мо	DAY

ANY VIOLATIONS (Reference all attachments here)


3THER MONITORING REQUIRMENTS. PLEASE ATTACH AN ADDITIONAL PAGE FOR COMMENT AND EXPLANATION OF ANY VIOLATIONS, AS NECESSARY.

e used. PAGE 1 OF 1

RECEIVED

Tit Division Cl Water Feliulian Control

ATTACHMENT II TDEC CORESPONDENCE



ATTACHMENT IV

COVER LETTER FOR THE MONITORING WELL ABANDONMENT

AND

CORRECTIVE ACTION SYSTEMDECOMMISSIONING REPORT

(Letter Report without attachments)





Antea USA, Inc. 5000 Peachtree Industrial Parkway, Suite 160 Norcross, Georgia 30071 USA www.anteagroup.com

April 4, 2013

Mr. Drew Storm, P.G.
Division of Underground Storage Tanks
Tennessee Department of Environment and Conservation
Nashville Environmental Field Office
711 R.S. Gass Boulevard
Nashville, Tennessee 37243

RE: Monitoring Well Abandonment and Corrective Action System Decommissioning Report

Former BP Service Station - BP Site No. 24368

222 Shelby Avenue
Nashville, Tennessee
TDEC Facility ID. No. 5-190964
Antea Group Project No. TN24368131

THE Division Gi Water

Dear Mr. Storm:

AnteaTMGroup is pleased to submit this Monitoring Well Abandonment and Corrective Action System Decommissioning Report to the Tennessee Department of Environment and Conservation (TDEC), Division of Underground Storage Tanks for Former BP Service Station No. 24368. The site is located at 222 Shelby Avenue in Nashville, Tennessee. A site map, Figure 1, depicting pertinent site features, is presented in Attachment I. In a correspondence dated January 18, 2013, TDEC required the proper abandonment of all monitoring wells and the decommissioning of the Corrective Action System (CAS) associated with the site. A copy of TDEC's January 18, 2013 correspondence, as well as an Extension Request letter (submitted to TDEC on March 5, 2013) are presented in Attachment II.

Antea Group contracted Tri-State Testing Services, Inc. (TN License Number 769) to abandon the wells at the site. From February 11 through 13, 2013, Antea Group field representatives supervised the proper abandonment of eight (8) existing wells (MW-1, MW-2, MW-4, MW-13, RW-1, RW-2, RW-3, and RW-4). Because the property owner re-asphalted the site, the sixteen (16) previously abandoned and destroyed wells (MW-3, MW-5, MW-6, MW-7, MW-7R, MW-8, MW-9, MW-10, MW-11, MW-12, MW-14, MW-14A, MW-15, MW-16, MW-17, and MW-18) could not be located during the well abandonment activities.

Monitoring well abandonment activities were completed at the site in accordance with Section II.M of the TDEC 2006 Environmental Assessment Guidelines. The depth of each well was gauged prior to abandonment, and the wells were pressure-grouted to the top of casing with a grout consisting of 95% Portland cement and 5% bentonite. The disturbed ground in the asphalt and concrete areas were restored with concrete to maintain the surface integrity. Photographs of the eight (8) abandoned wells are provided as Attachment III.



Antea Group contracted SEMS, Inc. (SEMS) to properly decommission and remove the CAS from the site. On February 22, 2013, SEMS field representatives decommissioned the CAS, in accordance to the CAS Checklist. A copy of the completed CAS Checklist is presented as **Attachment IV**.

On March 26, 2013, two soil waste drums and one sludge waste drum (generated during the deactivating and decontaminating of the site's CAS) were transported to Domermuth Environmental Services, located in Knoxville, Tennessee for offsite management and the wastes will be properly disposed of in the Waste Connections' - Scott Solid Waste Landfill in Oneida, Tennessee. A copy of the drum disposal Non-Hazardous Waste Manifest is presented in Attachment V.

The CAS pad will be removed, and final site restoration activities will be conducted, once TDEC has removed the CAS from the site.

If you have any questions regarding this submittal please contact me at (770) 825-1227 or Carla Nascimento at (908) 547-3834.

Sincerely,

Kenneth L. Brooke, P.E.

Project Manager

ken.brooke@anteagroup.com

Antea Group

Cc: Antea Group Files (Norcross)



Signature Pages

We, the undersigned, certify under penalty of law, including but not limited to penalties for perjury, that we will abide by the CAP Guidelines as established by Rule 1200-1-15-.06(10)(a) and the approved CAP, and that the information contained in this report including any attachments, is true, accurate and complete to the best of our knowledge, information, and belief. We further agree to submit all remediation information in accordance with the reporting formats as provided in the CAP Guidelines. Additionally, we agree to attend any meeting as scheduled and required by the Division. We are aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for intentional misrepresentations.

<u>Janet Wager</u> Owner/Operator (Print name)	Signature	Dager	8/2 Date	97/13
BP Representative	0 0	U		
Title (Print)				RECEIVED
				JUL 1 5 2013
				TR Bivisian Of Waler

STATE OF TOLOS COUNTY OF Harris


Sworn to and subscribed before me by Janet J. Wager on this date

March 27, 2013 . My commission expires June 12, 2015.

Dehoie M. Anderson Dellui M. Unduson 3/27/2013

Notary Public (Print name) Signature Date

Stamp/Seal



Fellutian Central

We, the undersigned, certify under penalty of law, including but not limited to penalties for perjury, that we will abide by the CAP Guidelines as established by Rule 1200-1-15-.06(10)(a) and the approved CAP, and that the information contained in this report including any attachments, is true, accurate and complete to the best of our knowledge, information, and belief. We further agree to submit all remediation information in accordance with the reporting formats as provided in the CAP Guidelines. Additionally, we agree to attend any meeting as scheduled and required by the Division. We are aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for intentional misrepresentations.

Kenneth L. Brooke, P.E.

P.E. or P.G. (Print name)

Signature Date

PE No. 100891

Stamp/seal

Tennessee Registration #

COUNTY OF

Sworn to and subscribed before me by Kennettt

My commission expires

Notary Public (Print name)

Date

KAREN STEPHENSON

Stamp/Seal

TR Bidsian Of Water Pellutian Centre'

